



## QUALITY ASSURANCE REQUIREMENTS

Subcontractor/Supplier shall provide a Certificate of Conformance (C of C) on all precision measuring equipment used, certifying that the equipment is calibrated and maintains traceability to the National Institute of Standards and Technology (NIST).

**Subcontractor Work: One copy of the C of C shall be submitted to the Purchasing Agent/Subcontract Administrator before beginning the contract.**

## QUALITY NOTE 21