



QUALITY ASSURANCE REQUIREMENTS

The vendor must submit, with each shipment one copy of a certification by the manufacturer's Quality representative certifying that the shackles furnished are manufactured and tested at 2.2 times the Safe Working Load (SWL). Lot numbers must be on the certification and material. Material must be stamped or forged with SWL, size, and manufacturer.

The certification shall include the Working Load Limit (WLL) in pounds, proof load test in pounds, and the minimum ultimate test in pounds (breaking load).

Any material received without certification, lot numbers and without proper markings shall be rejected and returned at the vendor's expense.

QUALITY NOTE 31