



QUALITY ASSURANCE REQUIREMENTS

An ISO 17025 accredited calibration certificate shall be provided certifying that the equipment is calibrated and maintains traceability to NIST.

Any equipment received without the certificate will be process as nonconforming material.

QUALITY NOTE 22