



## QUALITY ASSURANCE REQUIREMENTS

The vendor shall provide proof test certification for the purchased item by either the manufacturer or vendor per ASME B30 or other applicable industry standards. Each item shall be stamped, forged or tagged with critical information such as Working Load Limit (WLL), size, manufacturer and serial number. The proof test certificate shall include this same information (for traceability) and clearly indicate the WLL and proof test load in pounds.

**Any material received without certification or not properly marked (including serial number) shall be rejected and returned at the vendor's expense. If a traceable proof test certificate cannot be provided, the vendor must clearly indicate this information prior to purchase order award.**

## QUALITY NOTE 31