



QUALITY ASSURANCE REQUIREMENTS

The vendor shall submit, with each shipment one copy of a certification by the manufacturer's **Quality** representative certifying that the material furnished is manufactured and tested at 2.2 times the safe working load (SWL). Lot numbers shall be on the certification and material. Material shall be stamped or forged with SWL, size, and manufacturer.

The certification shall include the Working Load Limit (WLL) in pounds, proof load test in pounds, and the minimum ultimate test in pounds (breaking load).

Any material received without certification, lot numbers and without proper markings shall be rejected and returned at the vendor's expense.

NOTE: *Crosby brand is exempt from the certification requirement.*

QUALITY NOTE 31